



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM	
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

COUNTY: **Halifax**

PERMIT NO.: **SLAS-42-04**

FILE TYPE: **COMPLIANCE**

Date of Site Inspection: 8/7/2012 **Date of Last Inspection:** 3/16/2012

FACILITY NAME AND ADDRESS:

*A.M. Powell III
Powell's Septic Tank Service
PO Box 395
Roanoke Rapids, NC 27870*

GPS COORDINATES:

N: 36.40802

W: -77.69317

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: *Allie Powell*
Telephone: *252-537-2450*
Email address:
Fax: *252-535-4907*

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS: *Chester Cobb*

STATUS OF PERMIT: *Active*

EXPIRES: *12/1/2015*

PURPOSE OF SITE VISIT: *Routine*

STATUS OF PAST NOTED VIOLATIONS:

No violations noted on the previous inspection conducted on 3/16/12.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Signage present to both sides of the path as you get to the site.
2. Path to site was in good shape.
3. All boundary markers were up. Boundary markers are painted (red, yellow, white) 2 X 4 stakes in the ground. Markers are easily visible.
4. No septage discharges noticed outside of the permitted boundaries.
5. No thick applications or spot dumps noticed today.
6. Field B had been harvested recently. Field A will soon need to be harvested. Some broadleaf weeds noticed in the fields.
7. No application at time of inspection. pH not checked.
8. No objectionable odors noticed.
9. No change in the area noticed that would affect setback distances.
10. Records not checked.

Please contact me if you have any questions or concerns regarding this inspection report.



Chester R. Cobb

Regional Representative

Phone: (919) 707-8283.

Sent on: 7/23/13		Email		Hand delivery	X	US Mail		Certified No. <u> </u>
------------------	--	-------	--	---------------	----------	---------	--	-------------------------